

**PRODUCT INFORMATION SHEET**

These items were imported by: -  
 Just 1 Source & Supply Limited, Barton Hill, Whitwell, York. YO60 7JX  
 Telephone: 01653 617718 - [www.just1source.com](http://www.just1source.com)

These items comply with the requirements of the EU Regulation 2016/425 & Regulation 2016/425 on personal protective equipment, as amended to apply in GB, in line with the harmonised and designated standard(s) referenced below.

**NOTE:** - Declarations of Conformity can be found at [www.just1source.com](http://www.just1source.com)

**Limitations of use:**

EN 388:2016 + A1:2018, EN ISO 21420:2020 - The overall classification of gloves with two or more layers does not necessarily reflect the performance of the outermost layer. Gloves should not be worn when there is a risk of entanglement by moving parts or machinery.

The EN 388 test results shown below are taken from the palm area of the glove.

**EN 388:2016 + A1:2018**



**EN ISO 21420:2020**



Test	Performance Level
<b>EN 388:2016 + A1:2018</b>	
Abrasion	<b>4 (Scale 1-4)</b>
Blade Cut (Coup Test)	<b>2 (Scale 1-5)</b>
Tear	<b>4 (Scale 1-4)</b>
Puncture	<b>3 (Scale 1-4)</b>
ISO 13997 Cut (TDM)	<b>X (Scale A-F)</b>
Impact Protection	<b>(P if passed)</b>

ISO Cut Level	A	B	C	D	E	F
<b>Newtons</b>	<b>≥2</b>	<b>≥5</b>	<b>≥10</b>	<b>≥15</b>	<b>≥22</b>	<b>≥30</b>

Performance levels are measured where the highest number indicates the best protection.  
 "X" indicates that the product has not been tested against this risk


Product Code: - **PRED 1-HV** Size: **10**  
 Product Description: - Predator Hi-Vis Tiger Rigger Glove


Gloves providing protection against mechanical risks.

Maintenance: examine gloves for damages, splits and holes before each use. Always replace damaged gloves.

Disposal – Dispose of used gloves as instructed by your local authority

STORAGE: Store in dry ambient conditions	AFTERCARE: No Cleaning Treatment
--	----------------------------------

 EU Type Certification issued by **Intertek Italia Spa**,  
 Via Guido Miglioli,2/A - 20063 Cernusco sul Naliglio  
 (MI) Italia – **Notified Body 2575**

 UK Type Certification issued by **ITS Testing Services (UK) Ltd**,  
 Centre Court, Meridian Business Park,  
 Leicester. LE19 1WD – **Approved Body AB 0362**